





























































Промышленная швейная машина строчки зиг-заг Aurora A-20U100DZ

190 шаблонов декоративной строчки

Single-axis System Pattern(1)

Pattern No	Pattern Figure	Pattern No	Pattern Figure	Pattern No	Pattern Figure
1		11		21	
2		12		22	
3		13		23	
4		14		24	
5		15		25	
6		16		26	
7		17		27	
8		18		28	
9		19		29	
10		20		30	































Single-axis System Pattern(2)

Pattern No	Pattern Figure	Pattern No	Pattern Figure	Pattern No	Pattern Figure
31		41		51	
32		42		52	
33		43		53	
34		44		54	
35		45		55	
36		46		56	
37		47		57	
38		48		58	
39		49		59	
40		50		60	































Single-axis System Pattern(3)

Pattern No	Pattern Figure	Pattern No	Pattern Figure	Pattern No	Pattern Figure
61		71		81	
62		72		82	
63		73		83	
64		74		84	
65		75		85	
66		76		86	
67		77		87	
68		78		88	
69		79		89	
70		80		90	

Single-axis System Pattern(4)

Pattern No	Pattern Figure	Pattern No	Pattern Figure	Pattern No	Pattern Figure
91		101		111	
92		102		112	
93		103		113	
94		104		114	
95		105		115	
96		106		116	
97		107		117	
98		108		118	
99		109		119	
100		110		120	

Single-axis System Pattern(5)

Pattern No	Pattern Figure	Pattern No	Pattern Figure	Pattern No	Pattern Figure
121		131		141	
122		132		142	
123		133		143	
124		134		144	
125		135		145	
126		136		146	
127		137		147	
128		138		148	
129		139		149	
130		140		150	

Single-axis System
Pattern (6)

Pattern No	Pattern Figure	Pattern No	Pattern Figure	Pattern No	Pattern Figure
151		161		171	
152		162		172	
153		163		173	
154		164		174	
155		165		175	
156		166		176	
157		167		177	
158		168		178	
159		169		179	
160		170		180	

181-190 are for different sizes of Crescent shapes, such as below:

